

# Annexure D

## BUILDING SAFETY CERTIFICATE

No. 27

Dated: 09/10/25

It is certified that the existing building "Gurukul Bal Govind Academy", Vill- Begampur, Bahraich- 271801 (name and address of the building or premises) is having block(s)/Floor(s) as per details below:

Details Of Block in School	Block (1)
No. of Floors in the Block	G+1

The building is owned/occupied by building "Gurukul Bal Govind Academy", Vill- Begampur, Bahraich - 271801 (name and address of the Institution) have complied with the Building safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of Rural Engineering Dept. (Name of Department/ Govt.) on 09.10.2025 (Date of inspection) in the presence of Mr. Sitaram, Manager, "Gurukul Bal Govind Academy", Vill- Begampur, Bahraich - 271801 (name and addresses of the Manager/ Secretary or his representatives) and that the building/premises is fit for occupancy for running school with effect from 09.10.2025 for a period of 02 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. School building is designed according to National Building Code 2005 standards.
2. The school building is earthquake resistant.
3. The school building is built according to the plan.

Issued on 09.10.2025 at Bahraich, by AE/RED (Designation), Bahraich, U.P.

Signature with Seal: 

Name: \_\_\_\_\_

Designation: सहायक अभियन्ता

Name & Address of Department/ Office: ग्रामीण अभियन्त्रण विभाग  
प्रखण्ड-बहराइच



कार्यालय  
सहायक अभियन्ता (ग्रामीण)  
वि०खं० चित्तौरा जनपद बहराइच

पत्रांक:- 441

दिनांक:- 16-09-2023

सेवा में,

श्रीमान बेसिक शिक्षा अधिकारी,  
जनपद बहराइच

विषय:- गुरुकुल बाल गोविन्द एकेडमी ग्राम बेगमपुर वि०खं० चित्तौरा जनपद बहराइच का नेशनल बिल्डिंग कोड - 2005 के अन्तर्गत अनापत्ति प्रमाण पत्र जारी करने के सम्बन्ध में -

सन्दर्भ:- विद्यालय भवन हेतु आवेदन पत्र दिनांक 14.09.2023।

महोदय,

उपरोक्त विषयक संदर्भित पत्र के अनुपालन में स्कूल भवन का निरीक्षण किया गया।

1. स्कूल भवन फ्लैट स्ट्रक्चर पर है तथा दो तल निर्मित है।
2. स्कूल भवन में पर्याप्त वेंटिलेशन है तथा ठंड व गर्म से बचाव के लिए पर्याप्त व्यवस्था है।
3. स्कूल भवन में निकास हेतु पर्याप्त व्यवस्था है।
4. स्कूल भवन में पहुंचने हेतु सम्पर्क मार्ग पर स्थित है।

भवन निर्माण की गुणवत्ता नेशनल बिल्डिंग कोड - 2005 के मानकों के अनुरूप प्रतीत होता है तथा सुरक्षा के दृष्टि से भी सुरक्षित है।

प्रतिलिपि:-



*Manoj Kumar*  
सहायक अभियन्ता (ग्रामीण)  
वि०खं० चित्तौरा जनपद बहराइच

